

# Bayfield County Land Records Department

THIS IS NOT A CERTIFIED LAND CORNER RESTORATION DOCUMENT

WI ID #	4409062000
Section	06
Town	44
Range	9
PLSS location	E 1/4 6
Monument Found	1 1/2" IP
Condition of Monument	Undisturbed
Date of field work	05/22/02
Northing	361420
Easting	654614
Latitude	46.323680
Longitude	-91.530290
Date recorded	N/A
Set by	N/A
Date of perpetuation	5/14/1975
Perpetuated by	R.R.S. ?
Comment	POSITION FITS MID POINT DISTANCE POSSIBLE WRONG CORNER
Rate of Coordinates	GPS sub-meter
Picture #1	79
Picture #2	N/A
Stamped	

Photo of Monument



**DISCLAIMER NOTE:** This project involved a reconnaissance recovery of suspected PLSS corners – it is not to be construed as comprehensive retracement and recovery. This may or may not be the correct location of said PLSS corner. This location can only be used for a PLSS Inventory Assessment.

**NOTE:** Northing and Easting values are referenced to the Bayfield County Coordinate System. Latitude and Longitude values are in decimal degrees and in WGS 84 Datum.