

Bayfield County Land Records Department

THIS IS NOT A CERTIFIED LAND CORNER RESTORATION DOCUMENT

WI ID #	4509353300
Section	35
Town	45
Range	9
PLSS location	MC 35/36
Monument Found	FENCE POST
Condition of Monument	Undisturbed
Date of field work	05/21/02
Northing	363595
Easting	673583
Latitude	46.329860
Longitude	-91.455250
Date recorded	N/A
Set by	N/A
Date of perpetuation	6/20/1949
Prepetuated by	DAY
Comment	DAY'S PLAT OF SURVEY
Rate of Coordinates	GPS sub-meter
Picture #1	54
Picture #2	N/A
Stamped	

Photo of Monument



Double click for larger photo

DISCLAIMER NOTE: This project involved a reconnaissance recovery of suspected PLSS corners – it is not to be construed as comprehensive retracement and recovery. This may or may not be the correct location of said PLSS corner. This location can only be used for a PLSS Inventory Assessment.

NOTE: Northing and Easting values are referenced to the Bayfield County Coordinate System. Latitude and Longitude values are in decimal degrees and in WGS 84 Datum.